

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

TI-36111
1/6




Figure 1. Charge-Pump PLL (Prior Art)




Fig. 7

T1-36111
216

Figure 2. Differential Relaxation VCO (Prior ART)

T1-36111
3/6




Figure 3. VCO gain curve. (X-axis is the V_{c1}, Y-axis is the VCO frequency F_{osc})

(Prior Art)

TI-36111

4/6




Figure 4. Idea to change VCO gain at low frequencies.

T1-36111

5/6




Figure 5. Diode-Connected MOS to Reduce VCO Gain at Low Frequency




Figure 6. Current Injection to Reduce VCO Gain at Low Frequency